den,	
Conn	
A.A	
·	
ORM	
140	

Owner Nicholas and Victoria Baiad
Owners' Address 26 E. Pearl Street, Danbury, Connecticut
Property Appraised 28-28 River Street, Danbury, Connecticut. Known as
lot 12 block 6 on Redevelopment Map (tax parcel 5 SW side River
Street), consisting of a 4 family frame dwelling on an industrial zoned lot.
Recording Information Vol. 327 Pg. 122. Est. of Saleem Abboud (by order of
Probate Court to Nichelas and Victoria Baiad) (\$4,000) 12/14/57.
Assessment: Land
Building Improvements 1.690 Taxes
Total Assessment
Photographs and/or Sketch



Inside bot



River St.

Seale1"=40'

0

Market Value (Appraisers Final Valuation)

Land	. \$2,500	
Land Improvements		
Building Improvements	4.000	
	\$6,500	
Total	Marie Land Wolfer Carlotte level land with the Land	

Certification: I certify that I inspected the property on January 11, 1960 and that this appraisal has been made in accordance with standards of ethics and practice of The American Institute of Real Estate Appraisers.

Date of Appraisal January 21, 1960

Parl G-Kaffinheiger 9.
Approxisers Signature

## NEIGHBORHOOD DESCRIPTION Zoning Industrial Boundaries Neighborhood boundaries coincide with the Redevelopment area which lies westerly of Main Street. Character and Trend Neighborhood is a combination of old factories, warehouses, stores and tenements and a few dilapidated dwellings. Residential LAND DESCRIPTION non-white. Trend is downward. Size 48.65 x irregular Description This lot at street level in the front rises gradually to the rear. Utilities Sewer, water, gas, electricity, curbs, gutters and sidewalks. Land Improvements Retaining wall at rear. Highest and Best Use of Property As 4 family residence. LAND VALUATION Please refer to Market Data - on page 4. Subject lot is too small to have much potential for industrial or warehouse use. There is always some possibility of future combination with adjoining land for industrial use, and for this reason the land is worth more than the cheaper house lots cited on page 4. Land Value . \$50 per fr. ft. \$2433 (.51 per sq. ft.) Land Improvements . . . . \_ incl. BUILDING DESCRIPTION AND COST APPROACH 4 Family **Building Class** Age over 70 Condition Quality\_\_\_\_ Poor Poor Number of Baths Number of Rooms Number of Lav. none Number of Stories Total Height 201 or less Average Story Height 101 or less Single Floor Area Total Area Shape: Approximate Square Rectangle or Slightly Irregular Long Rectangle or Irregular Very Irregular **Total Unit Cost Per Square Foot** (From Page 3) Correct for Size and Shape. 1.04 Height . Dist. Multiplier . Total Adjusted Cost Per Square Foot Total Area 1733 X \$7.62 Per Square Foot Replacement Cost \$13,206 Less Depreciation 9,244 55 Functional 15 Economic Physical Building Value By Cost Approach . . Value of other Building Improvements porches (front and rear) Add Land Value (include land improvements) 2,500 TOTAL VALUE BY COST APPROACH . . . . 6,602

Comments: Small rear addition 12.5 x 13 is only 10 or 12 year old.

However property is in generally poor condition and subject to substantial physical depreciation and some functional depreciation.

Only access to second floor is through outside wooden stairs. Property would be condemned under usual standards of inspection.

Page 2

Lump Sum Additions

1	FOUNDATION:	DEBUKH TION	Component Part Check List	Unit Cost
	Concrete Conc. I	Unit Cost		
	Other	.18		
2	EXTERIOR WALL: Co	na Dlask		
2.		nc. Block		
		sonry & Steel Sash sonry Veneer		
		tal Clad		
	Conc. Me	tal Panel	Wood_Clapboard	
	Other	tur runer_		1.49
3.	ROOF STRUCTURE:			1.49
	Conc. Conc. & T			
	(Divide Cost by Number of Stor	ies) 62/2		21
4.	ROOF COVER:	.03/2		.31
	Asbestos Shingle	Galv. Iron	Shakes	
	Built-up Composition_			
	Composition Shingle	Slate	Wood Shingle	
	Other			
	(Divide by Number of Stories)	09/2		.05
5.	FRAME:	Conc. Reinf.	Steel Fireproofed	
		Steel Open	Wood	
	Other			
_	Decrease% for bearing			.14
6.	FLOOR:		Hardwood	
	Brick on Ground	Reinf. Conc.	Softwood X	
7	Other_			.63
1.	FLOOR COVER:	Linoleum	Softwood on Conc.	
	Asphalt Tile	Marble	Tenazzo	
	Cork Tile	Rubber Tile	Tile, Ceramic_	
	Other	Slate	Vinyl Tile	
0	CEILING:			
0.	On Wood Structure	0- 51		
	Other Viola Structure X	On Steel or C	Conc. Structure	
	Other			.16
9.	INTERIOR CONSTRUCTION:	Single Res.	Other	
		Ave		7 20
			· many	1.30
10.	HEATING and COOLING:	Gravity Furnace	Steam with Boiler	
	Forced Air	Heaters	Steam without	
		Hot Water Radiat	ors Boiler	
	Gas Steam Radiators			
	Other	Combin	ed Heat & Air Conditioning	0
11.	ELECTRICAL: Min.	Few	Ave Many	- 1-
				14
12.	PLUMBING: Min	Few	Ave Many	.67
				ATAMES TOTAL
	DASLMENT: Unit Cost \$1.5	O A Area 750	Divided by Total Area 1733	.66
	Total Ur	nit Cost / Square Foo	t	5.73
Porc	hes: Area 250 an et XI	Init Cost 67 110	Value \$350 less 60%	dommontatt
Gard	age	#1.40	= 210	deblectarion
	ouildings		\$140.	

## MARKET DATA APPROACH (Please refer to MARKET DATA BOOK for complete details for the transactions used below).

- LAND VALUE The following land sales were considered in comparison:
  - Land 1. \$150 per fr. ft. \$1.50 per sq. ft. Altho this is an industrial lot located on Rose St. it has a special value to the purchaser as it gave him a back entrance from his Main Street property. It also is close to Main Street and takes on business value.
  - Land 2. \$40 per front ft., \$.30 sq. ft. This is a fairly good comparison an industrial lot.
  - Land 5. At \$34 per front ft., .20 per sq. ft., and land 6 and land 7 at \$30 per fr. foot, .30 per sq. ft. are examples of cheap lot sales in B Res. Zone. Subject lot in industrial zone, even with limited size is worth more.
  - Land 19. At \$52 per front ft. .15 per sq. ft. is a larger (3 acre) industrial parcel which still is worth comparing.
- PROPERTY VALUE

Compare With:

(1-3F)- 2 at \$7.31 per sq. ft. \$1188 per Rm. -Subject not as good.

(1-3F)- 3 at \$6.75 per sq. ft. \$1350 per Rm. -Subject not as good. (1-3F)- 4 at \$2.00 per sq. ft. \$250 per Rm. -This is subject property -This is subject property. Sale at \$4,000 with approval of Probate Court was to the nephew of the deceased and is believed have been well below Market Value

(1-3F)- 5 at \$5.81 per sq. ft. \$1359 per Rm. -Subject not as good.

(1-3F)- 7 at \$6.63 per sq. ft. \$1279 per Rm. -Subject not as good. (1-3F)- 8 at \$3.83 per sq. ft. \$1389 per Rm. -Subject not as good. (1-3F)- 9 at \$3.83 per sq. ft. \$770 per Rm. -Subject property not as

good as this, but this and #4 are the closest comparisons.

(1-3F)-11 at \$6.00 per sq. ft. \$1333 per Rm. -Subject property not as good physically and not nearly as good location-wise.

From a Market standpoint subject property is worth approximately \$3.50 to \$3.75 per sq. ft. by comparison or from \$6,100 to \$6500. Since the comparisons made were with 1 to 3 family dwellings (because of the size of this house) it is probable that this being a four family with 4 full baths will be at the higher end of the bracket. My cost approach at \$6600 bears this out. My final estimate of value is therefore \$6500.

RENTAL DATA GROSS MULTIPLIER INDICATED VALUE

Based on gross multipliers found in my study of 1-3 family residences, I think that gross multiplier should be approx. 60 times the monthly rental.

\$6,000

Rentals on 4 apartments 60 total \$100 per month.