Owners' Address 64 Elm Street, Danbury, Connecticut

Property Appraised Known as #64-66 Elm Street, Danbury, Connecticut, being Redevelopment parcels 2 and 3 Block 10 or Tax parcels 8 and 9.

south side of Elm St.

Vol. Page 87 Joseph Buzaid to Nazhia Buzaid Recording Information

January 22,

#64 #66

\$2060. Assessment: Land . \$2810 **Building Improvements**

4400 . 2850 \$6460. Total Assessment . \$5660

Taxes

Photographs and/or Sketch

See Tracing Attached



Market Value (Appraisers Final Valuation,

\$16,000

Land Improvements Building Improvements (both buildings10,000

\$26,000 Total

Certification: I certify that I inspected the property on January 28, 1960 and that this appraisal has been made in accordance with standards of ethics and practice of The American Institute of Real Estate Appraisers.

Date of Appraisal February 13, 1960

The Friday Press, Box 297, Meriden, Con

NEIGHBORHOOD DESCRIPTION
Zoning Business 2
Boundaries Neighborhood boundaries coincide with the Redevelopment area
which lies westerly of Main Street.
Character and Trend Neighborhood is a combination of old factories, warehouses,
stores and tenements and a few dilapidated dwellings. Immediate area of
Elm Street is stores and tenements. Residential occupancy is non-white. LAND DESCRIPTION Trend is downward.
Size Per sketch Frontage 123* total Area 4650 sq. ft.
Description Grade of land falls off from street to the rear.
Utilities Sewer, water, gas, electricity, curbs, gutters and sidewalks.
Land Improvements None
III I I I I I I I I I I I I I I I I I
Highest and Best Use of Property Store and tenement.
LAND VALUATION Please refer to Market Data - on page 4.
Based on a study of comparable on page 4A, land on Elm St. is worth
\$200 per front foot for 100 ft. depths. In my opinion New Street
near Elm is worth \$100 per front foot for 100 ft. depths. See below
under Comments for figuration correcting for depth and corner influence.
under comments for lightation correcting for depth and corner influence.
Land Value
Land Improvements
Total Land
BUILDING DESCRIPTION AND COST APPROACH #64 Elm Street
Occupancy Store and tenement Building Class D
Quality Low Age Over 60 Condition 1st floor good, 2nd floor poor
Quality Low Age Over 60 Condition 1st floor good, 2nd floor poor
Number of Rooms Number of Baths Number of Lav. 2 Number of Stories Total Height 20 or less Average Story Height 10 or less
Single Floor Area 1117 Total Area 2234
Shape: Approximate Square Rectangle or Slightly Irregular X Long Rectangle or Irregular
Very Irregular
Total Unit Cost Per Square Foot (From Page 3) . \$ 5.83
Correct for Size and Shape
Height
Dist. Multiplier
Total Adjusted Cost Per Square Foot
and the same of th
Total Area 2234 X \$8.50 Per Square Foot Replacement Cost
Less Depreciation
Physical 50% Functional 5% Economic
Building Value By Cost Approach
Value of other Building Improvements Porches
Add Land Value (include land improvements)
TOTAL VALUE BY COST APPROACH
In round figures \$29,400
Comments: Assume 58' on Elm to 70' depth, and 65 ft. on New to 70' depth.
\$200 x 84% depth factor - \$158 x 58' Elm St \$9164
100 x 68% corner influence factor - 668 per fr. ft 66800
7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7
177
The state of the s
so ft This nurchase had an evicting comming atotion and the
sq. ft. This purchase had an existing service station on it. Also the lot had 3 street frontage (or double corner influence.)

71'4" 240 S. S. 12.30 17.20 EIMI STREET 24'8"

	BUILDING DESCRIPTION —	- Component Part Check List	
1.	FOUNDATION:		Unit Cost
	Concrete Conc. Post Mason	ry X Wood Blocking	
	Other	,	.18
2	EVERIOR WALL C. BL.	£4	
۷.	EXTERIOR WALL: Conc. Block	Stone	
	Asbestos Siding Masonry & Steel Sash	Stucco	
	Brick Common Masonry Veneer Masonry Veneer	Tile, Clay Tilt-up Conc	
	Brick Face Metal Clad Conc Metal Panel	Wood	
	Other		1.75
3.			1.()
•	Conc. Conc. & Tile Wood F	rame with Wood Sheathing X	
	Other .71/2	Tellio Willi Wood Dilockilling	
	(Divide Cost by Number of Stories)		.36
1.	ROOF COVER:		
	Asbestos Shingle Galv. Iron	Shakes	
	Ruilt up Composition V Pall	Tile	
	Composition Shingle Slate	Wood Shingle	
	Other . 24/2		
	(Divide by Number of Stories)		.12
	FRAME: Conc. Reinf.		
	Cast Iron Columns Steel Open	Wood_ X	
	Other		
	Decrease% for bearing wall.		. 24
	FLOOR: Conc. on Ground		
	Brick on Ground Reinf. Conc.	Softwood X	
ď	Other	Property of the Park Control of the Park Contr	.73
	FLOOR COVER: Linoleum 50% 3		
	Asphalt Tile Marble	Tenazzo	
	Cork Tile Rubber Tile	Tile, Ceramic	
	Hardwood on Conc. Slate	Vinyl Tile	
	Other		.22
3.	CEILING:		
	On Wood Structure X On Steel or	Conc. Structure	00
	Other		.20
9.	INTERIOR CONSTRUCTION: Single Res	Other	
•		Many	.40
		- Many	. 40
).	HEATING and COOLING: Gravity Furnace	Steam with Boiler	
	Forced Air 50% x .43 Heaters	Steam without	
	Furnace Floor or Wall Hot Water Radio	itors Boiler	
	Gas Steam Radiators Radiant Floor		
	OtherCombi	ned Heat & Air Conditioning	.21
			h.c
١.	ELECTRICAL: Min Few_X	Ave Many	.46
2.	PLUMBING: Min Few_X	Ave Many	.34
	BASEMENT: Unit Cost 1.25 X Area 1117	Divided by Total Area 2234	ATA.62
	Total Unit Cost / Square Fo	pot	\$5.83
oro	ches: Area 4 x 20 X Unit Cost	Value	
iar	rage 6' x 14' - 164 sq. ft.	@ \$1.50 - \$246 less 5%	depreciatio
	tbuildings		\$110.70

MARKET DATA APPROACH

RENTAL DATA GROSS MULTIPLIER

INDICATED VALUE

APPRAISAL REPORT

Owner		TR. Tange
Owners' Addre	f was do t	A CONTRACTOR OF THE PROPERTY O
- поренту гарри	(See reverse side)	
Recording Info	rmation	
Assessment:	Land	Tax Rate
	Building Improvements	Taxes
	Total Assessment	
Photographs a	nd/or Sketch	



	Land												
	Land Improvements .						1	begreg	Misson +	a sul e	Manihii et		
	Building Improvements					-	ethor	ra may	L grabli	12 made	9 10 90(5)		
	Total					Han	prong	rei bnol	eBufeni O sia su	PelaV	Blay Sh		
Certificat has been m Appraisers.	ion: I certify that I insp ade in accordance with sta	ecte	d the	e prof et	opert thics	y on and pro	actice	of The	Americ	c an Ins	and that t titute of	nis appra Real Est	isal ate

NEIGHBORHOOD DESCRIPTION			
Zoning	AND DESCRIPTION OF THE PARTY OF	minus	
Boundaries			
Character and Trend			the state of the s
LAND DESCRIPTION			
Size	Frontage	Area	
Description			- A Transaction Company
Utilities			
Land Improvements			
Highest and Best Use of Property			
LAND VALUATION Please refer to Ma	rket Data - on page 4.		
THE RESERVE OF THE PARTY OF THE	Carps relative to the same		
		West of the second	
Land Value			
Land Improvements			
Total Land			
BUILDING DESCRIPTION AND COST A			
Occupancy 2 fam. residence a			
	ge 1870 Condit	ion Very poor	
Number of Kooms Nu	mber of Baths 2	Number of	
Number of Stories 2 Total			Height 101 or less
	angle or Slightly Irregular		angle or Irregular
Very Irregular	angle or Slightly Irregular	Long Rect	angle or irregular
Total Unit Cost Per Square Foot	(From	n Page 3) .	\$ 5.48
Correct for Size and Shape	_		7.10
Height			
Dist. Multiplier	1.2	g	1.28
Total Adjusted Cost Per Square Foot .			\$ 7.01
Total Area 2700 × \$7.01			Balley Colleges and the last
Replacement		Consider their	\$18,927
Less Deprecia		Landina V. India	14,195
Physical 70% Functional 5% Econ			75%
Building Value By Cost Approach	ch	· · · · · ·	\$ 4,732
Value of other Building Improve	ments	· · · · · · · · · · · · · · · · · · ·	Marking .
Add Land Value (include land in	marayamanta)		
Add Land Value (include land in TOTAL VALUE BY COST APPROACH			
TOTAL TALOR DI COST ATTROACH			The second second
Comments:	A STATE OF THE PARTY OF THE PAR		Landa De La Contra
series had be during a dominant and the	e material sales and to be a	Land a last Astronomy	

	BUILDING DESCRIPTION — Component Part Check List	
1.	FOUNDATION:	Unit Cost
	Concrete Conc. Post Masonry_ X Wood Blocking_ × Other	.13
2.	EXTERIOR WALL: Conc. Block Stone	
	Asbestos Siding Masonry & Steel Sash Stucco	
	Brick Common Masonry Veneer Tile, Clay	
	Brick Face Metal Clad Tilt-up Conc.	
	Conc. Metal Panel Wood X	
	Other	1.49
3.	ROOF STRUCTURE:	
	Conc. Conc. & Tile Wood Frame with Wood Sheathing	
	Other .63/2	774
1	(Divide Cost by Number of Stories) ROOF COVER:	.31
7.		
	Asbestos Shingle Galv. Iron Shakes Built-up Composition Roll_ Tile	
	Composition Shingle Slate Wood Shingle	
	OtherO9/2	
	(Divide by Number of Stories)	.05
5.	FRAME: Conc. Reinf. Steel Fireproofed	
	Cast Iron Columns Steel Open Wood X	
	Other	- 1
	Decrease% for bearing wall.	.14
6.	FLOOR: Conc. on Ground Hardwood	
	Brick on Ground Reinf. Conc. Softwood X	19
_	Other	.63
1.	FLOOR COVER: Linoleum Softwood on Conc	
	Asphalt Tile Marble Tenazzo	
	Cork Tile Rubber Tile Tile, Ceramic	
	Hardwood on Conc. Slate Vinyl Tile Other	0
8	CEILING:	
0.	On Wood Structure X On Steel or Conc. Structure	
	Other	.16
9.	INTERIOR CONSTRUCTION: Single Res Other	
	.Min Few X Ave Many	1.30
10	HEATING 1 COOLING. C	
10.	HEATING and COOLING: Gravity Furnace Steam with Boiler Forced Air Heaters Steam without	
	Furnace Floor or Wall Hot Water Radiators Boiler	
	Gas Steam Radiators Radiant Floor	
	Other Combined Heat & Air Conditioning	0
11.	ELECTRICAL: Min. X Few Ave. Many	.14
12.	PLUMBING: Min. X Few Ave. Many	.40
	BASEMENT: Unit Cost 1.50 × Area 1317 Divided by Total Area 2700	.73
	Total Unit Cost / Square Foot	\$5.48
Porc	ches:AreaX Unit CostValue	
Gar	age	
Out	buildings	
Lum	p Sum Additions	

MARKET DATA APPROACH A. Land. In analysing my land value, I have taken the following transactions into consideration (please refer to Market Data Book).

Land 1 at \$150 per front ft., \$1.50 per sq. ft. Although this is an industrial lot and subject a business zoned lot, it is close to Main Street and as such has an element of comparison. Not as good as subject property.

Land 12 at \$473 per front ft. and \$2.37 per sq. ft. will break down to \$270 per front ft. or \$2.70 per sq. ft. for 100' depth, using 4-3-2-1 depth rule.

Land 13 at \$402 per front ft. and \$2.01 per sq. ft. will break down to \$230 per front ft. or \$2.30 per sq. ft. for 100' depth using 4-3-2-1 depth rule. It is adjacent to Land 12.

Land 24 at \$160 per front ft. and \$2.46 per sq. ft. works out to \$200 per front ft. or \$2.00 per sq. ft. for 100' depths. It is in the same block as subject property but at the far end away from Main Street, an inside lot on the south side of Elm Street.

B. Property

Please refer to Market Data book, "Stores and Apartments" section. In analysing my transactions, I have graded each one "low" or "average". I have added \$1.00 per sq. ft. to the three transactions where the building had no basement.

The average per sq. ft. figure of 10 transactions in the low category is \$6.52 per sq. ft. The range in the "low" category is primarily within the \$4.50 per sq. ft. to \$7.50 per sq. ft. bracket.

After careful study, my conclusion is that the stores and apartment properties on Elm Street on the average lie within the lower end of this range, primarily from \$4.50 to \$5.50 per sq. ft.

The store and tenement is fairly typical. Store is in better than average condition, upstairs is in poor condition. Ordinarily I will use \$5.00 to \$5.50 on this store, but because of corner location I should use \$6.00 to \$6.50.

The house is very poor and worth perhaps \$3.50 per square foot by comparison, but because of corner location, I will use \$4.50.

Store and Tenement

\$13,404 to \$14,521 12,150 to 12,150

\$25.554

\$26,671

RENTAL DATA

GROSS MULTIPLIER

INDICATED VALUE

See Income Approach

INCOME APPROACH Store is owner-occupied, for which they charge themselves \$125 per month. The second floor apartment is vacant. It did bring \$55 per month but is in poor condition. The two apartments in the other building bring \$55 and \$45 respectively and there is a small store in that building not rented.

Gross Income Estimate

#64	Store @ \$1.75 per sq. ft. 2nd floor - 5 rooms @ \$10 per room per month	\$1954 600
#66	10 rooms at \$10 per room per month each Small store	1200 300
	Less: Allowance for vacancies and lost rent	\$4054 405
	Gross Effective Income	\$3649
	Less Expenses: Taxes Insurance Fire \$191 Liab. 200 391 Water Repairs Management 350 146	1432
Net	Less interest on Land \$1600 x 8%	\$2217 1280
	Income attributable to improvements	\$ 937
Capi	talized at 13% (8% Interest plus 5% straight line depreciation based on estimated 20 year remaining life) Add land	7207
	Total	\$23,207

COMMENTS Interest rate used above is based on the following estimate:

6% mortgage rate on 50% - 3%

10% equity rate on 50% - 5%

Interest rate 8%

Note: The 50% of value 6% mortgage loan is the most likely in this area. Equity requirements of from 10-13% are applicable. However since I am using straight line depreciation, vacancy allowance, and realistic economic life, I will use 10%.

CORRELATION OF APPROACHES

Indication of Cost Approach
Indication of Market Approach
Indication of Income Approach
29,400
25,500 to \$26,700
23,200

Because of the good corner location, this property has better than average possibilities. Therefore, I am inclined to go along with my somewhat optimistic Market Approach.

Final Estimate \$26,000