APPRAISAL

58 Division Street Danbury, Connecticut

CITY & STATE Danbury, Connecticut BY ROBERT N. NOCE ASSOCIATES PROJECT NAME Mid-Town East U. R. Project PROJECT NO. Connecticut R - 104 BLOCK 6 PARCEL NO. 1

ADDRESS 108 - 110 WHITE & CANAL STREETS OWNER HAROLD & BENJAMIN BUSN ITZKY DESCRIPTION OF BUILDINGS

STORES & TENEMENT



DATE BUILT 1910 PURCHASE DATAL/10/46VOL.219 PAGE 465

: PURCHASE PRICE NOT Known

: IMPROVEMENTS SINCE PURCHASE WITH APPROXI-

: MATE COST AND NECESSARY STRUCTURAL REPAIRS

ASSESSMENT Land 7720	See Addenda
Buildings 13150	int: DIMENSIONS and AREA 45 x 79.9/70 x 44.7
	: 44.85 x 74.95 = 3362 sq. ft.
TOTAL 20870	ZONING: GB-10 TOPOGRAPHY Grade Level
TAXES SPECIAL ASSESSMENTS	None Known
HIGHEST and BEST USE	Present Uses

VALUATION

PIFTY THOUSAND ONE HUNDRED DOLLARS

\$50100.00

CERTIFICATION

We hereby certify that we have no interest, present or contemplated, in the property and that neither the employment to make the appraisal nor our compensation is contingent on the value of the property. We certify that we have personally inspected the property and that, according to our knowledge and belief, all statements and information in this report are true and correct.

DATE 11/29/67

Robert N. Noce, S.R.A.

(A) SUSNITZKY STORE (Corner)

TYPE - STORE & TENEMENT

EXTERIOR - Foundation - Concrete & cinder block
Pet store has wood front
Walls - solid Brick -1 Brick & stucco

Windows- Steel sash, fllo digar Store -wood frames, flos steel frames

Screens-Nene

Gutters and Leaders - None

Roof -Built up - flat

Porches- Store entrance

Dormers - Mone

Condition - Good

INTERIOR - Basement - Part - dirt - old

Heat -1 Oil Burner Steam furnese - 2 unit Gas Heaters

Hot Water Supply -3 Gas Het Water Heaters

Plumbing -Copper & Galvarised

Wiring - 110 & 220

Other stores see att. sheets

Rooms-- lst Floor - 2 stores - Susnitzky-main store-45 x 26-

2nd Floor - 12 rooms, 2 toilets, bad condition - not rentable as is - not used

3rd Floor -

Floors -Asphalt Tile

Walls -Wood panel - store - new

Ceilings -Block - 10'6", 2nd. fl. 9'2", cellar 6'7"

Kitchen -3oda Fountain

Bathroom =1 = \$, (Cigar store has 1 toilet, 1 lavatory. 2 toilets upstairs, - fountain - 1 sink

Closets

Fireplace *

Condition - lat. - Good, - 2nd. - Poor

Outbuildings - None

RENT - Cwner occupied

TYPE - STORE & TENEMENT

EXTERIOR - Foundation -Concrete Block & Stone

Walls -Brick & New Wood Front

Windows - Steel Sash

Screens - North

Gutters and Leaders - None

Roof . Built up flat

Porches - Store Intranse

Dormers- Neme

Condition - Pair

INTERIOR - Basement - Partial - dirt

Heat - Unit Gas Heaters - hot air

Hot Water Supply - Gas Hot Water heater

Plumbing - Copper & Galvanised

Wiring -110-220

Rooms-- lst Floor = (3) = main store area (1 sink room-Aquarius a Office

2nd Floor - See Cigar Store

3rd Floor

Floors - Asphalt Tile - New

Walls . New Plywood

Ceilings - Block - new - 11'6" high

Kitchen

Bathroom - 1 toilet & 1 lavatory, 1 large sink aquarium

Closets *

Fireplace 🥌

Condition -Fair to Good

Outbuildings - None

RENT - \$150,00 per month

(B) OFFICE A & J AMUSEMENT CO. CANAL STREET TYPE - Store & Tenement

EXTERIOR - Foundation - Concrete & Cinder block

Walls -folid Brick

Windows - Steel Sash

Screens - Home

Gutters and Leaders - None

Roof -Built - up flat

Porches - store Entrance

Dormers -None

Condition - Good

INTERIOR - Basement - Pert Dirt

Heat - Unit Gas hot air

Hot Water Supply - 1 Gas hot water heater

Plumbing - Copper & Galvanised

Wiring - 110- 220

Rooms-- 1st Floor - 2 offices

2nd Floor

3rd Floor

Floors -Asphalt

Walls - Wood panelled - to ceiling

Ceilings - 11. 6" - blook ceiling

Kitchen

Bathroom - 1 Toilet - 1 Lavatory


Closets -

Fireplace

Condition - Fair to Poor - needs redescrating

Outbuildings - None

RENT - \$60.00



COST APPROACH

LAND Market Data Approach does not involve a breakdown of component parts. Separate land value is not necessary. Property residual approach in capitalization process does not involve a land value.

BUILDINGS

The subject building is old and outmoded in type of construction, layout and architecture. In view of these factors and the amount of Market Data available for study, the Cost Approach is inapplicable.

ELEMENTS OF COMPARABILITY:	SUBJECT	87 COMP. # 9	COMP. # 15	COMP. #14
Quality of Location	GOOD	GOOD	GOOD	GOOD
Quality of Construction	GOOD	GOOD	GOOD	GOOD
Physical Condition	ATR/GOOD	PAIR	GOOD	GOOD
No. of Stories	2	3	1 - 2	4
Sq. Ft. Area Excl. Base.	6320	4110	7516	8556
Price per Sq. Ft. Gross Bldg. Area	•	\$9.00	\$9.05	\$7.59
No. of Rooms (Residutl.)	12		•	•
Price per Room	•		•	•
Facilities: Kitchen	40	•	•	•
Bath	LAV.	LAV.	LAV.	LAV.
Heat	GAN/UNIT	STRAM OIL	STBAM OIL	STEAM GA
Others				
Lot Size Square Feet	3362	2408	7725	S 1100
Income (Actual & Vac. Est.)	•		\$13380	•
No. Floors or Apts. Occ. at Time of Sale UNITS	3	VACANT	3	1
Gross Income Multiplier			5	•
Date of Sale	**	7/12/66	8/1/67	3/12/65
Sales Price	•	\$37500	\$68000	\$65000
INDICATED COMPARABLE VALUE	OF SUBJECT	PROPERTY:	\$50600	
CONCLUSIONS & REASON FOR MA	RKET APPROA	CH VALUE:		
ST-9 Smaller, better	logation	, less lan	d.	
CP-15 Larger, better				
ST-lh Larger, better				
After analysis and adj	ustment t	he indicate	ed value p	er sq.
ft. of building area	s \$8.00.	This is t	he soundes	t basis
for comparison in this		,		
a con wompone and one one with		****		

ADDENDA

Heighberhood uses are predominantly business in character, with all future growth along these lines,

There have been no major inprovements in recent years. The building was renovated on the first level after a major fire some years ago. The second floor can be put to very limited use such as storage in its present poor condition.